


Quick Start Guide – PH1000 pH Sensor


Procedures for connecting and configuring the Greenspan PH1000 Sensor. Further details in the Sensor Manual included on the Greenspan CD.

You should have received:

- Certificate of Conformance Sheet
- CD Manuals & Software
- Greenspan PH1000 Sensor
- Cable Options per order



Sensor may be fitted with optional removable cable



PH1000 provides pH measurement as a calibrated analogue outputs 4-20mA, over the Sensor Full Scale range. Sensor requires a nominal 12V DC power supply, but will operate from 10-14V DC